

## DESCRIPTION

PES 180 is a two-component paste for being used as a high strength structural adhesive. The system is based on toughened epoxy novolac resins, silicon steel alloy, and fillers for chemical and corrosion resistance.

# TYPICAL APPLICATION

Body Coat	PES 180 @ 1/8" thickness
-----------	--------------------------

#### PERFORMANCE DATA

${\tt Compressive Strength}  {\tt ASTM}$	C-57911,000 psi
Tensile Strength ASTM	C-3072,400 psi
Bond Strength ASTM	C-4541>1,000 psi
$\hbox{Hardness (Shore D)}\hbox{ASTM}$	D-224687
DensityASTM	C-905 165 pcf (2.64 gm/cm <sup>3</sup> )
Heat Resistance	300°F

### STORAGE & INSTALLATION

Storage Environment	
Application Temperature, ambient	40–95°F
Application Temperature, substrate40	
Shelf Life	24 months
Pot Life, @ 77°F	40 minutes
Tack Free Time, @ 77°F	2.5 hours
Light Movement @ 77°F	4 hours
Full Loading @ 77°F	2 days
Contact with Chemicals @ 77°F	3 days

Material cures more slowly at cooler temperatures, and working time will be substantially reduced at higher temperatures. In hot weather, material should be cooled to 65°F to 80°F prior to mixing and application to improve workability and avoid shortened pot life. The data shown above reflects typical results based on laboratory testing under controlled conditions. Reasonable variations from the data shown above may result.

# CONSIDERATIONS & LIMITATIONS

- 1. Do not thin with solvents unless advised to do so by PES.
- 2. Prepare substrate according to "Surface Preparation" portion of this document.
- Always use protective clothing, gloves and goggles consistent with OSHA regulations during use. Avoid eye and skin contact. Do not ingest or inhale. Refer to Material Safety Data Sheet for detailed safety precautions.
- 4. For industrial/commercial use. Installation by trained personnel only.
- 5. Do not apply when the temperature is below 40°F (5°C) or the relative humidity is above 85%.
- 6. Do not apply when there is moisture on the metal surface or is likely to be deposited by subsequent condensation.
- Do not apply when the working environment is likely to be contaminated by oil/grease from adjacent equipment or smoke from kerosene heaters or tobacco smoking.

# **PES 180**

TECHNICAL DATA SHEET

# **Structural Adhesive**

#### BENEFITS

- Excellent dry-heat abrasion resistance
- Excellent impact resistance
- Excellent chemical and corrosion resistance
- Long working times
- Cures down to 40°F

### RECOMMENDED USES

- Bonding Ceramic Tile, Steel, or Aluminum
- High Strength Bonding to Similar or Dissimilar Substrates

### GENERIC DESCRIPTION

Epoxy Novolac

# STANDARD COLOR

Gray

#### PACKAGING

25 kg Units

# MIX RATIO

1:1 BY VOLUME

#### COVERAGE

25 sq. ft/ unit @ 1/8" thickness

#### SURFACE PREPARATION

This product can be applied to substrate(s) that have been prepared according to the following Surface Preparation Guidelines:

### Apply only to blast cleaned surfaces.

- Clean up loose contamination and degrease with a rag soaked in an effective cleaner, e.g. methylethyl ketone (MEK), which does not leave a residue.
- 2. Use only an angular abrasive to give a minimum depth of profile of 3 mils.
- 3. Blast-clean the metal surface to achieve near white finish SSPC SP 10.
- After blasting, metal surfaces should be coated before any possible oxidation.

Metal must have  $<3\mu g/cm^2$  chloride and  $<5\mu g/cm^2$  sulfate contamination.

#### INSTALLATION STEPS

1. **Mixing:** Pre-blend Part A and Part B before beginning. Measure equal volumes of Part A and Part B. Place Part B into Part A and mix together using a mechanical mixer, such as a Jiffy mixer, scrape the sides and bottom of the container and mix an additional minute to ensure material is homogeneous.

Warning: Improperly mixed material will not cure properly.

- 2. Application: Apply PES 180 onto prepared surface with a plastic applicator, spatula, or trowel blade. Press down firmly to remove entrapped air and insure maximum bonding to the surface. If necessary, additional layers should be applied when the first layer is still soft, within 2 hours at 77°F. If the overcoating time is exceeded, brush blast the cured material before any further application.
- 3. **Cleaning:** Clean tools with a non-flammable and low-evaporating cleaner. Always wear gloves when using this product. Wash hands, arms and face with warm soapy water.

For further information, contact: Plant Equipment & Services, Inc.

5401 Hwy 21 W Bryan, TX 77803 Ph: 979-779-8700

pes1@pes-solutions.com www.pes-solutions.com

1R:1H C / DOC PES-180 Rev 1/11